From: <u>Hadwin, Erik</u>

To: louis.martin@la.gov; sherri.courtney@la.gov; regenia.taylor@la.gov; karen.price2@la.gov; Greg.

Fife/R6/USEPA/US@EPA; Sherman, Robert; Bordelon, David

Cc: Howard, Larry

Subject: Bayou Corne Natural Gas Seep-Activities conducted on Friday, August 24, 2012 between 1600 hrs to 2400 hrs

and on Saturday, August 25, 2012 between 0000 hrs to 0730 hrs

Date: 08/25/2012 07:20 AM

Activities Performed by EPA START personnel on Friday, August 24, 2012 between 1600 hrs to 2400 hrs and on Saturday, August 25, 2012 between 0000 hrs to 0730 hrs:

- 24/7 air monitoring/oversight was conducted at the drilling site. Duties included review of facility's real-time monitoring data with the facility/contractor personnel, review of alarm readings and also calibration and maintenance records for facility's air monitoring instruments, and hand-held monitoring at 9 monitoring points. Parameters monitored included CO, H₂S, VOCs, LEL, and O₂. All readings were below the low action levels and with normal O₂ readings. Monitoring was conducted using the MultiRae. During the 1600 hrs to 2400 hrs shift on August 24, 2012, the hand-held monitoring at the 9 monitoring points was limited to 1 round and a portion of the 2ndth round due to due to heavy/moderate rain from approximately 1955 hrs to 2220 hrs. Between 0000 hrs to 0730 hrs on August 25, 2012, EPA START completed 4 rounds of hand-held monitoring at the 9 monitoring points.
- No additional problems or issues were encountered.



Erik Hadwin

Project Scientist

Weston Solutions, Inc.

an employee-owned company 13702 Coursey Blvd., Bldg #7, STE A Baton Rouge, LA 70817 225-297-5406 225-293- 8339(fax) 225-773-9104 (cell) erik.hadwin@westonsolutions.com

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return email and delete this email from your system. Thank you.

****************** ATTACHMENT NOT DELIVERED ****************

This Email message contained an attachment named image001.jpg

which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments



sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.